



BIT Inspection Technology

(NDT/ Weld Inspection Training / Consultancy/ Third Party Inspection)

Technical Justification

Doc. no. BIT/TJ/ 002



Location : BIT Inspection Technology, Chennai, India

UT Operator : Saikumar, PCN UT 3.1,3.2,3.9

Analyst : R.Baskar, ASNT Level 3 RT,UT,PT,MT,VT,ET / PCN NDT level 3 RT,UT,PT,MT / AWS – SCWI / CSWIP 3.2

1. Abstract

Gap analysis performed to distinguish echo response analysis between

Vertically oriented lack of fusion defects at fusion face in a **main member** with lack of fusion defect at fusion face in a **branch member**




Figure - 1




Figure - 2




Figure - 3

Note:

Figure -1: Scanning pattern as per position - 2 as shown in Figure - 2, targeting lack of fusion defect at fusion face in a **branch member**

Figure -2: Scanning pattern

Figure -3: Scanning pattern as per position - 2 as shown in Figure - 2, targeting vertically oriented lack of fusion defects at fusion face in a **main member**

2. Reference documents

- EN 1713 - UT characterization of indication
- AWS D1.1 - Structural welding code - Steel


3. Gap Analysis Reference

- Main member segment - 20" x sch 80 (25mm WT), Branch pipe - 6" Dia x sch 80 (11mm WT)
- Reference block : 38mm thick with 3mm SDH
- Weld specimen material: Carbon steel
- Reference (DAC): 45 dB


4. Parameter synchronized

- Both lack-of-fusion defects kept at same depth of approximately 2mm from scanning surface in a TKY weld connection in order to maintain similar beam path and hence same material attenuation.
- So echo response is only based on type and orientation of defect

5. **Echo response of** vertically oriented Lack of fusion defects at fusion face in a main member **and** **lack of fusion defect at fusion face in a branch member @ reference 45 dB**



Vertically oriented lack of fusion defects at fusion face in a **main member @ DAC (45 dB)**




Lack of fusion defect at fusion face in a **branch member @ DAC (45 dB)**


Observation:

Parameters	Vertically oriented lack of fusion defects at fusion face in a main member @ DAC (45 dB)	Lack of fusion defect at fusion face in a branch member @ DAC (45 dB)
Amplitude % FSH	<p>15 % FSH</p> <p>Note: From the above CRT display noticed that, ultrasonic sound response from <u>vertically oriented lack of fusion defects at fusion face in a main member</u> is reduced due to vertical orientation of lack of fusion, which results loss of sound energy due to reflection to other direction and mode conversion. That is the reason amplitude response is reduced and amplitude height is below the DAC reference curve.</p>	<p>43% FSH</p> <p>Note: From the above CRT display noticed that, ultrasonic sound response from <u>lack of fusion defect at fusion face in a branch member</u> is optimized due to lack of fusion defect orientation close to normal to sound beam, which results maximum response. That is the reason amplitude response is increased and amplitude height is above the DAC reference curve even at only DAC reference dB.</p>
Time base width	1 mm	1mm

6. **Echo response** vertically oriented Lack of fusion defects at fusion face in a main member **and** lack of fusion defect at fusion face in a **branch member** @ reference **45 dB + 6 dB**



Vertically oriented lack of fusion defects at fusion face in a **main member**@DAC (45 + 6 dB)



Lack of fusion defect at fusion face in a **branch member** @ DAC (45 + 6 dB)

Observation:

Parameters	Vertically oriented lack of fusion defects at fusion face in a main member @ DAC (45 + 6 dB)	Lack of fusion defect at fusion face in a branch member @ DAC (45 + 6 dB)
Amplitude % FSH	<p>28 % FSH</p> <p>Note: Noticed from the above CRT display noticed that, sound response equivalent to 3mm \varnothing reflector (touches DAC reference curve) only at DAC (45 + 6 dB)</p> <p>Reference block : 38mm thick with 3mm SDH</p>	<p>90% FSH</p> <p>Note: From the above CRT display noticed that, ultrasonic sound response from lack of fusion defect at fusion face in a branch member is optimized due to lack of fusion defect orientation close to normal to sound beam, which results maximum response. That is the reason amplitude response is increased and amplitude height is above the DAC reference curve.</p>
Time base width	1 mm	1mm

7. Echo response Vertically oriented planner defects at fusion face in a main member and planner defect at fusion face in a branch member @ reference 45 dB + 12dB



Vertically oriented lack of fusion defects at fusion face in a main member @ DAC (45 + 12 dB)




Lack of fusion defect at fusion face in a branch member @ DAC (45 + 12 dB)


Observation:

Parameters	Vertically oriented lack of fusion defects at fusion face in a main member @ DAC (45 + 12 dB)	Lack of fusion defect at fusion face in a branch member @ DAC (45 + 12 dB)
Amplitude % FSH	<p>60 % FSH</p> <p>Note: Noticed from the above CRT display noticed that, sound response above the DAC reference curve, only at DAC (45 +12 dB)</p> <p>Reference block : 38mm thick with 3mm SDH</p>	<p>>100% FSH</p> <p>Note: From the above CRT display noticed that, ultrasonic sound response from lack of fusion defect at fusion face in a branch member is optimized due to lack of fusion defect orientation close to normal to sound beam, which results maximum response. That is the reason amplitude response is increased and amplitude height is above the DAC reference curve and even above full screen height.</p>
Time base width	1 mm	2mm

8. Noise indication interpretation



Lack of fusion defect at fusion face in a **branch member** @ DAC (45 + 12 dB)



9. Summary of observation

Parameters	Vertically oriented lack of fusion defects at fusion face in a main member	Lack of fusion defect at fusion face in a branch member	Remarks
Amplitude comparison			
Amplitude % FSH @ DAC	15 (Note -1)	43 (Note - 2)	
Amplitude % FSH @ DAC + 6 dB	28	90	
Amplitude % FSH @ DAC + 12 dB	60 (Note - 3)	>100 % FSH	
Time base comparison			
Time base width in mm @ DAC	1	1	No variation observed
Time base width in mm @ DAC + 6 dB	1	1	No variation observed
Time base width in mm @ DAC + 12 dB	1	2	Variation observed, but ignorable

Note -1: Ultrasonic sound response from vertically oriented lack of fusion defects at fusion face in a main member is reduced due to vertical orientation of lack of fusion, which results loss of sound energy due to reflection to other direction and mode conversion. That is the reason amplitude response is reduced and amplitude height is below the DAC reference curve.



Note -2: Ultrasonic sound response from lack of fusion defect at fusion face in a branch member is optimized due to lack of fusion defect orientation close to normal to sound beam, which results maximum response. That is the reason amplitude response is increased and amplitude height is above the DAC reference curve even at only DAC reference dB.

Note -3: Sound response above the DAC reference curve, only at DAC (45 +12 dB)

11. Conclusion



Ultrasonic testing of **Node** and **Nozzle** weld:

- While scanning and targeting fusion type of defects **at fusion face in a branch member**, recommend to use scanning sensitivity **DAC reference + 6 dB**



Lack of fusion defect at fusion face in a **branch member** @ DAC (45 + 6 dB)


- While scanning and **targeting fusion type of defects at fusion face in a main member**, recommend to use scanning sensitivity **DAC reference + 12 dB** and sizing by **- 6dB** from scanning sensitivity.



- Reason for the above recommendation

- While scanning and **targeting fusion type of defects at fusion face in a main member**, sound response reduced due to vertical orientation of expected fusion type of defects and sound beam meets the reflector at an angle, which results loss of sound energy due to reflection to other direction and mode conversion

- Scanning with **DAC reference level**, sound energy meets the vertically oriented reflector in a main member fusion face is **equivalent to 0.75mm Ø spherical reflector** (calculated with reference to distance law for side drilled hole) due to reflection to other direction and mode conversion not equivalent to 3 mm Ø spherical reflector in a reference block.
- Even scanning with DAC + 6 dB, achieved amplitude is **equivalent to 3mm Ø spherical reflector**. Take this as base and add + 6 dB more for scanning sensitivity. That is the reason recommend to use scanning sensitivity **DAC reference + 12 dB** and sizing by – 6dB from scanning sensitivity.
- Based on **difference in sound response**, we can clearly emphasize to NDT personnel.



Reference to distance law for side drilled holes (SDH)

$$A \propto \sqrt{\frac{r}{d^3}} \quad \text{where,}$$

r - radius of SDH
 d - distance from scanning surface (beam path)
 A - Amplitude height

The vertically oriented lack of fusion type reflector in a main member to the sound beam is equivalent to 0.75 mm Ø spherical reflector as shown in the below calculation

$$\frac{A_{(DAC)}}{A_{(defect)}} = \frac{\sqrt{\frac{1.5}{(40.5)^3}}}{\sqrt{\frac{r_{(defect)}}{(40.5)^3}}} = \frac{30}{15}$$

$$r_{(defect)} = 0.375 \text{ mm}$$

Ø of equivalent spherical reflector = 0.375×2
 $\approx 0.75 \text{ mm}$